

## NEW ENGINE REAR START LOCK OUT

THINK EMPLOYEE SAFETY AND HELP PREVENT POSSIBLE INJURIES





- Before your employees perform any service, lockout and isolate the rear engine start button to prevent possible injuries.
- Keep work place safe by controlling mechanical hazards, battery recharging and hydraulic hazards.
- Easy to install lock out is available for H and X coach models.

| PART#  | DESCRIPTION           | MODEL   | EFFECTIVE VIN#           |
|--------|-----------------------|---------|--------------------------|
| G34718 | LOCKING BOX ASM       | X3-COM  | E-5590 TO G-7299         |
| G34583 | ASSEMBLED LOCKING BOX | H3-45   | F-2953 TO J-0294         |
| G35064 | ASSEMBLED LOCKING BOX | X3-45   | G-5916 TO H-6179         |
| G35890 | ASSEMBLED LOCKING BOX | H3 & X3 | J-0294 (H3); E-5458 (X3) |

Freight is prepaid for all ground shipments

